



IMPORTANT  
Magnet Path  
and  
Proper Position at Sensor

Proper Orientation  
of  
Magnet to sensor

Sensitive Area

CompuLoad Scales  
4737 Ortega St. #24  
Ventura, California USA 93003  
[www.compuLoad-scales.com](http://www.compuLoad-scales.com)

Magnet Path  
During Lift